

Factura

Furnizor: S.C. AUTO COBALCESCU S.R.L.	Factura Nr. : SP3249339 Nr. Aviz ins. marfa : Data Fact.: 04.10.2019	CLIENT: Societate ALGORITHM RESIDENTIAL S3 SRL
Nr.Reg.Comert: J40/12025/1991 CUI: RO1590376 Sediul: STR. SPLAIUL UNIRII, NR. 311, SECTOR 3 BUCURESTI, ROMANIA	Conditii de plata: Card Banca Data Scadenta: 06.10.2019 Asigurator:	Nr.Reg.Comert: J40/5481/2017 CUI/CNP: RO37409960 Sediul: CALEA VITAN, NR.242, SECTOR 3 CALEA VITAN, NR.242, SECTOR 3
		Banca: Contul:
		Cod Client: 074931 Tel. Mobil: Tel./Fax.:
		Nr. O.R. : 320076944

Cota TVA: 19 %

Pag	Serie sasiu	Data reparatiei	Kilometraj		Nr inmatriculare	Tip APV	Data livrare		
1	VF1JL000161930275	04.10.2019	30152		B307ALG	JGM	04.10.2019		
Denumire produs sau servicii	Cod Reper	U.M.	Cant/ Timp	Red %	Pret Unit net	Valoare unit (fara TVA)	Valoare total (fara TVA)	Valoare TVA	
1	2	3	4	5	6	7	8	9	
Manopera									
OS DIAGNOST CIRCUIT DE FRANARE	MC010101	or	0,30		100,00	100,00	30,00	5,70	
OG INLOC PLACUTA DE FRANA SPATE	MC013231	or	0,80		100,00	100,00	80,00	15,20	
TOTAL (fara TVA) Manopera							110,00		
Piese									
*PLACUTE FRANA	410604868R	I	1,00		305,01	305,01	305,01	57,95	
TOTAL (fara TVA) Piese de schimb							305,01		

Numar ore facturate: 1,10 ore

TOTAL (fara TVA)	415,01
TVA	78,85
TOTAL de plata	493,86

Caroserie: 0374 102347/8

